

ThyssenKrupp

☒ Mandatory Risk Assessment

Hazard	RR	Controls	Tick	NR
Working at Height		RCD		
Electrocution	✓	Fire Extinguisher / Fire Blanket		✓
Energised Equipment, Plant, Services		Lock Out Tagout	✓	
Manual Handling		EWP / Scaffold		
Entanglement		Fall Arrest/PPE.		
Slip / Trip / Fall		Mechanical Lifting / 2 Man Lift / Breakdown Load		
Hazardous Substances		MSDS / Spill Kits		
Poor Housekeeping		Isolation, Barricades, Signage		
Crushing		Remove all Waste, and Trip Hazards		
Pinch Points		Insulation of Tools & Equipment		
		Lead Hooks, Lead Stands		

Every Visit: 1. Contact Customer ☐ 2. Ride Quality ☐ 3. Regular Checks ☐ 4. Emergency Telephone ☐		Maintenance Entered (Office):
---	--	--------------------------------------

Time In::..... AM PM Time Out:.....:..... AM PM

[illegible]

☒

Call Out Report

Repair: ☐ On Site Call: ☐ A/Hour Call: ☐ Charge: ☐ Group Fault: ☐ Follow Up: ☐

SWP: ☐ SWP on arrival: ☐ R.O.A.: ☐ Interference: ☐ Shut Down: ☐ Travel Time: 10:20 ☒ ☐

Time In: 10:40 ☐ ☒ AM PM SWP Released: 10:45 ☐ ☒ AM PM Time In Service: ☐ ☐ AM PM Time Out: 12:40 ☐ ☒ AM PM

Action Report: Released passenger. Lift stopped with max flight time error. Diagnostic tool required to reset controller. Shutdown

Call Out Entered (Office):

Fault Code: _____

Charge Client: ☒ Charge Other: ☐ Cash Charge: ☒ Customer Order Number: _____

Client Name: _____ Client Phone Number: _____

Client Address: _____

Client Signature: _____ Mechanic's Signature: _____

NSW	VIC	ACT	SA	WA	TAS	NT	QLD	NZ
1300 799 599	1300 799 599	1300 799 599	1300 799 599	1300 799 599	1300 799 599	1300 799 599	1300 652 899	9379 7798
			White-Customer...	Pink-Office...	Green-Motor Room			

731297 V1