



# EAGLE FIRE PROTECTION PTY. LIMITED.

A.B.N. 69 081 288 057

Unit 11/128 Station Rd, Seven Hills, NSW 2147

Phone: (02) 9620 8885 Fax: (02) 9620 8884 A/H Phone: (02) 9937 2145

Monday, 10 August 2015

Quote# 8003534

Steve Carbone

The Owners - Strata Plan 52948

C/- Raine & Horne Strata - Sydney

1-15 Fontenoy Road

Macquarie Centre NSW 2113

## Six Monthly Test Report and Quote

Test Date: 21/07/2015

Tester/s: Andrew Craig

Test Type: Six Monthly Test

Eagle Fire Protection is pleased to provide the results of the latest scheduled test and inspection. The following equipment failed when tested and requires further attention:

## Common Areas Of Building

### Equipment Type: Fire Extinguishers

<b>Equipment:</b> DCP 9kg Tag# EXT1			
<b>Location:</b> Roof area inside fire stairs, Level 7, Building B			
ITEM: 1	Requires extinguisher ID type sign	Supply and install fire extinguisher type sign	\$15.00
<b>Equipment:</b> Foam 9Litre Tag# EXT4			
<b>Location:</b> Adjacent Parking bay 153, Level B, Car Park			
ITEM: 2	Requires Location Sign	Supply and Install new Location Sign as required	\$15.00
<b>Equipment:</b> Foam 9Litre Tag# EXT7			
<b>Location:</b> Adjacent Parking bay 112, Level B, Car Park			
ITEM: 3	Refill Extinguisher	Leave loan extinguisher and refill extinguisher	\$92.00

Cost To Complete Repairs For Fire Extinguishers: \$122 + GST

### Equipment Type: Emergency and Exit Lighting

<b>Equipment:</b> EM 1x36 C			
<b>Location:</b> In store room level 8, Level 7, Building A			
ITEM: 4	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment:</b> EM 1x36 C			
<b>Location:</b> Inside fire stairs Level 8, Level 7, Building A			
ITEM: 5	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment:</b> EM 2x18 D Tag# 124			
<b>Location:</b> Inside fire stairs, Level 7, Building A			
ITEM: 6	Failed 90min Test	Supply and Install new 18W twin LED	\$285.00

<b>Equipment: EM 1x36 C</b>			
<b>Location: Inside fire stairs, Level 1, Building B</b>			
ITEM: 7	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: Oyster</b>			
<b>Location: Adjacent lift, Level 5, Building B</b>			
ITEM: 8	Failed 90min Test	Supply and Install new Oyster light	\$285.00
<b>Equipment: Exit EC CM SS</b>			
<b>Location: Adjacent unit 34, Level 5, Building B</b>			
ITEM: 9	Failed 90min Test	Supply and Install new standard Exit	\$185.00
<b>Equipment: EM 1x36 C</b>			
<b>Location: Inside fire stairs, Level 2, Building C</b>			
ITEM: 10	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: Oyster</b>			
<b>Location: Adjacent lift, Level 4, Building C</b>			
ITEM: 11	Failed 90min Test	Supply and Install new Oyster light	\$285.00
<b>Equipment: Exit EC CM SS</b>			
<b>Location: Adjacent unit 79, Level 5, Building C</b>			
ITEM: 12	Failed 90min Test	Supply and Install new standard Exit	\$185.00
<b>Equipment: EM 1x36 C</b>			
<b>Location: Inside fire stairs, Level 6, Building C</b>			
ITEM: 13	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 1x36 C</b>			
<b>Location: Above lift shaft door, Level 7, Building C</b>			
ITEM: 14	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 1x36 C Tag# 42</b>			
<b>Location: Inside fire stairs adjacent plant room door, Level 7, Building C</b>			
ITEM: 15	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 1x36 C</b>			
<b>Location: Inside fire stairs adj stairs to 8, Level 7, Building C</b>			
ITEM: 16	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 2X18 C</b>			
<b>Location: Inside fire stairs, Level 7, Building D</b>			
ITEM: 17	Failed 90min Test	Supply and Install new 18W twin LED	\$285.00
<b>Equipment: EM 1x36 C Tag# 170</b>			
<b>Location: Adjacent parking bay 155, Level B, Car Park</b>			
ITEM: 18	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 1x36 C Tag# 171</b>			
<b>Location: Adjacent parking bay 153, Level B, Car Park</b>			
ITEM: 19	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 2x36 C Tag# 187</b>			
<b>Location: Adjacent parking bay 16, Level B, Car Park</b>			
ITEM: 20	Failed 90min Test	Supply and Install new 36 watt twin LED	\$290.00
<b>Equipment: EM 1x36 C</b>			
<b>Location: Between parking bay 114 &amp; 142, Level B, Car Park</b>			
ITEM: 21	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 1x36 C</b>			
<b>Location: Adjacent lift motor room 3, Level B, Car Park</b>			
ITEM: 22	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00

<b>Equipment: EM 1x36 C Tag# 204</b>			
<b>Location: Adjacent parking bay 40, Level B, Car Park</b>			
ITEM: 23	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 1x36 C Tag# 205</b>			
<b>Location: Adjacent parking bay 71, Level B, Car Park</b>			
ITEM: 24	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 1x36 C Tag# 210</b>			
<b>Location: Adjacent parking bay 75, Level B, Car Park</b>			
ITEM: 25	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 1x36 C Tag# 213</b>			
<b>Location: Adjacent lift motor room 2, Level B, Car Park</b>			
ITEM: 26	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 1x36 C</b>			
<b>Location: Fire stairs Adjacent parking bay 19, Level B, Car Park</b>			
ITEM: 27	Failed 90min Test	Supply and Install new 36 Watt single LED	\$270.00
<b>Equipment: EM 2x36 C Tag# 237</b>			
<b>Location: Adjacent parking bay 39, Level B, Car Park</b>			
ITEM: 28	Failed 90min Test	Supply and Install new 36 watt twin LED	\$290.00
<b>Equipment: EM 2x36 C</b>			
<b>Location: in lift motor room 3, Level B, Car Park</b>			
ITEM: 29	Failed 90min Test	Supply and Install new 36 watt twin LED	\$290.00

**Cost To Complete Repairs For Emergency and Exit Lighting: \$6,970 + GST**

## **Summary Section**

### Inclusions/Exclusions:

All Prices quoted exclude GST

No allowance has been made for any additional works not included in the scope of this quote

No allowance has been made for painting and patching

No allowance has been made for working out of hours

No allowance has been made for working above 1.8m

Regards

Garry Riddle

Eagle Fire Protection

Mobile: 0406 533 226

Please send all Work Orders and correspondence to: [service@eaglefire.com.au](mailto:service@eaglefire.com.au)

This Quote is valid for 30 days and subject to our standard terms and conditions, available upon request.

